



SAFETY ALERT

THIS WALMART BRAND COFFEE MAKER CAUGHT FIRE DURING OFFICE USE. THE CAUSE OF THE FIRE IS UNDETERMINED BUT BELIEVED TO BE DUE TO THE AGE OF THE UNIT AND A PROLONGED PERIOD OF BEING PLUGGED IN.

COFFEE MAKERS SHALL BE

U/L APPROVED


PLACED ON A NON-COMBUSTIBLE SURFACE
PLUGGED DIRECTLY INTO A WALL RECEPTACLE
(NOT PLUGGED INTO SURGE PROTECTOR)

GOOD SAFETY PRACTICE IS TO UNPLUG COFFEE
MAKERS WHEN UNATTENDED OR NOT IN USE

USFOR-A THEATER OPERATIONAL SAFETY OFFICE
318-449-4830

SAFETY ALERT

11-008



SAFETY ALERT

SAFETY ALERT

11-008